

LIST OF NON - COMPLIANCE

17. Tuy Hoa Airport

NO.	Non Compliance	Regulation Reference	Mitigation Measure	Validity
1.	The total width of the taxiway and shoulder (about 23m) does not meet the minimum size of 25m for Code C aircraft.	3.10.1 MAS 1	<ul style="list-style-type: none"> - Develop coordination documents with ATC in developing operation measures and takeoff and landing operations. - Strengthen regular and unscheduled maintenance of taxiways and taxiway strip to ensure good operating conditions of taxiways. - Develop an airport emergency plan to respond to incidents. - Strict control of FOD on taxiways. 	25/4/2024
2.	No VOR Check-point publication at aerodrome	2.5.1.h, 5.2.12,5.4.4 MAS 1	<ul style="list-style-type: none"> - Announce non-compliant list on mass media (such as AIP...) for airlines to know. - Continue to maintain the safety management system; Meet the time required to record and coordinate the processing of reflections by airlines operators and relevant units. 	25/4/2024
3.	Technical specifications for the slope of the runway have not been announced	2.5.1.a, MAS 1	<ul style="list-style-type: none"> - Develop coordination documents with ATC in developing operation measures and takeoff and landing operations. - Strengthen regular and unscheduled maintenance of runway and runway strip to ensure good operating conditions of runway. - Develop an airport emergency plan to respond to incidents. - Strict control of FOD on taxiways. 	25/4/2024

4.	Stopway lights have not been installed yet	5.3.16 MAS 1	<ul style="list-style-type: none">- Carry out daily, periodic and unexpected inspections of runways pursuant to regulations.- Carry out assessment and report on runway surface condition (RCR) pursuant to regulations.- Continue to maintain the safety management system; Meet the time required to record and coordinate the processing of reflections by airlines operators and relevant units.	25/4/2024
----	--	--------------	--	-----------